

# Work Order ID 71534

Wednesday, July 06, 2011 11:27:01 AM



Page 1

Item ID: D3595-063-570

Accept



Setup Start



Revision ID:

Stop



Item Name: RUBBER CUSHION

Start Date: 7/6/2011 Start Qty: 25.00



Cust Item ID:

Required Date: 7/13/2011 Req'd Qty: 25.00



Customer:

Reference:

Approvals: Process Plan: C2 Date: 11/07/09 Tooling: \_\_\_\_\_ Date: \_\_\_\_\_  
QC: \_\_\_\_\_ Date: \_\_\_\_\_ SPC (Y/N): \_\_\_\_\_ Date: \_\_\_\_\_

Run Start



Stop



Sequence ID/ Work Center ID	Operation Description	Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
Draw Nbr	Revision Nbr								
D3595	Rev A								

100 0.00



FLOW WATER JET

Waterjet

Memo

0.00

FLOW CNC Waterjet

1-Cut as per Dwg D3595 ☐ Dwg Rev: A ☐ Prog Rev: A ☐ 2-  
Deburr if necessary

B11-7-12

(61)

110 0.00



QC2- Inspect parts off machine FAI/FAIB

QC

Memo

0.00

Quality Control

B11-7-12

120 0.00



QC8- Inspect parts - second check

QC

Memo

0.00

Quality Control

8/6/12

61

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: \_\_\_\_\_ PAR #: \_\_\_\_\_ Fault Category: \_\_\_\_\_ NCR: Yes No DQA: \_\_\_\_\_ Date: \_\_\_\_\_

Resolution: \_\_\_\_\_ Disposition: \_\_\_\_\_ QA: N/C Closed: \_\_\_\_\_ Date: \_\_\_\_\_

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

**NOTE:** Date & initial all entries

**Work Order ID 71534**

Wednesday, July 06, 2011 11:27:01 AM



Page 2

Item ID: D3595-063-570

Accept



Setup Start



Revision ID:

Stop



Item Name: RUBBER CUSHION

Start Date: 7/6/2011 Start Qty: 25.00



Cust Item ID:

Required Date: 7/13/2011 Req'd Qty: 25.00



Customer:

Reference:

Run Start



Approvals: Process Plan: \_\_\_\_\_ Date: \_\_\_\_\_ Tooling: \_\_\_\_\_ Date: \_\_\_\_\_

Stop



QC: \_\_\_\_\_ Date: \_\_\_\_\_ SPC (Y/N): \_\_\_\_\_ Date: \_\_\_\_\_

Sequence ID/  
Work Center IDOperation  
DescriptionSet Up/  
Run Hours

Tool ID

Tool #

Plan  
CodeAccept  
QtyReject  
QtyReject  
NumberInsp.  
Stamp

130

Identify as per dwg & Stock Location: *X-tube*

0.00

*ASS'Y*

Packaging

Memo

0.00

Packaging

*W* *11* *07* *12* *(61)*

140

QC21- Final Inspection - Work Order Release

0.00



QC

Memo

0.00

Quality Control

*11/7/13* *[Signature]**MF*  
*11-07-12*

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: \_\_\_\_\_ PAR #: \_\_\_\_\_ Fault Category: \_\_\_\_\_ NCR: Yes No DQA: \_\_\_\_\_ Date: \_\_\_\_\_

Resolution: \_\_\_\_\_ Disposition: \_\_\_\_\_ QA: N/C Closed: \_\_\_\_\_ Date: \_\_\_\_\_

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

**NOTE:** Date & initial all entries

# Picklist Print

Wednesday, July 06, 2011 11:26:58 AM

Page 1

Work Order ID: 71534



Parent Item: D3595-063-570



Parent Item Name: RUBBER CUSHION


Start Date: 7/6/2011

Required Date: 7/13/2011

Start Qty: 25.00

Required Qty: 25.00

Comments: IPP Rev:A New Issue 07-08-07 JLM Verified By:

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Issued	Status
D3595  Rubber Cushion (per sq ft)		Manufactured	No			100	sf	342.3000	0.0196	0.515789			



B11-7-12

Location

Loc Qty

Loc Code

MAT

342.3

68954

342.3

68954

6

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: \_\_\_\_\_ PAR #: \_\_\_\_\_ Fault Category: \_\_\_\_\_ NCR: Yes No DQA: \_\_\_\_\_ Date: \_\_\_\_\_

Resolution: \_\_\_\_\_ Disposition: \_\_\_\_\_ QA: N/C Closed: \_\_\_\_\_ Date: \_\_\_\_\_

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries






DESIGN <i>PH</i>	DRAWN BY <i>PH</i>	<b>DART AEROSPACE LTD</b> HAWKESBURY, ONTARIO, CANADA	
CHECKED <i>[Signature]</i>	APPROVED <i>[Signature]</i>	DRAWING NO. D3595	REV. A SHEET 1 OF 1
DATE 07.02.07		TITLE RUBBER CUSHION	SCALE NTS
A	07.02.07	NEW ISSUE	

RELEASED  
07.02.14 *[Signature]*

## SPECIFICATION CONTROL DRAWING



SHOP COPY  
RETURN TO  
ENGINEERING  
UNCONTROLLED COPY  
SUBJECT TO AMENDMENT  
WITHOUT NOTICE  
WORK ORDER  
NO. 71534

*C L 11/07/06*

EG: 0.75"x4.30" RUBBER CUSHION = D3595-075-430

### NOTES

- 1) MATERIAL: BLACK NEOPRENE SHEET, 0.125 THICK,  
80 DUROMETER (REF DART SPEC. M-NEO80-S.125)
- 2) FINISH: NONE
- 3) ALL DIMENSIONS ARE IN INCHES
- 4) TOLERANCES ARE PER DART QSI 018 UNLESS OTHERWISE NOTED

Copyright © 2007 by DART AEROSPACE LTD

THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.